





Z AXIAL PRESET GAUGE

MODEL: EZDI-100



ZDI - 100


- Height 100mm.
- The magnetic base with installation on - off.
- The design in a direct way return to be zero.
- Indicator of 0.01mm dial gauge.
- Capacity of 80kg magnetic base.
- Weight : 1.9 kgs



How to use Z Axial Preset Gauge :

1. Turn the button of setting - zero from "USE" to "TEST".
2. Press down, the small indicator will show "0", keep your hand and then adjust indicator to be zero at long - needle.
3. Turn the button of setting - zero to "USE" before use.
4. Put on the workpiece, turn the magnetic base to "ON", cutter touch probe side, when the long - needle and short - needle moving to "0" at the same time, the distance of the cutter with workpiece is 100mm.

MODEL: EZOP-50



FEATURES

1. Height 50mm.
2. With the magnetic base.
3. The red lamp will light up when touched.
4. Accuracy 0.002mm.
5. Combine vertical and horizontal in one unit.
6. Net weight 0.5kg.